



Enlarged City School District

Building	# of Samples Submitted	# of Results Received	# of Samples Above 15 ppb.	Location	Remediation
JSHS	139	107	13	Bathroom sink - room 162	Left & center faucet - Faucet, supply lines and piping have been removed and will be replaced.
				Girls room 232 – Left sink	Replace & retest
				Boys room 230 – Left sink	Replace & retest
				Bathroom 210 – left sink	Replace & retest
				Room 207	Replace & retest
				Boys bathroom 252 Left	Replace & retest
				Room 261 sink	Replace & retest
				Room 265 sink	Replace & retest
				Room 267 sink	Replace & retest
				Girls bathroom – 253 right	Replace & retest
				Room 253 bathroom middle	Replace & retest
				Room 253 bathroom left	Replace & retest



Microbac Laboratories, Inc., New York Division

CERTIFICATE OF ANALYSIS

J6J0914

Cortland City School District

Neal Helms
1 Valley View Drive
Cortland, NY 13045

Project Name: SSHS

Project / PO Number: 170841
Received: 10/14/2016 09:55
Reported: 12/06/2016 15:58

Analytical Testing Parameters

Client Sample ID: 232 Girls Room Sink on Right HS-1
Lab Sample ID: J6J0914-01
Sample Type: Grab

Collected By: RBN-Client
Collection Date: 10/13/16
Collection Time: 05:00

Analyses Subcontracted to: Microbac Laboratories, Inc. - Chicagoland

Metals	Result	Limit	PQL	Units	Note	Prepared	Analyzed
Method: EPA 200.8 Rev 5.4							
Lead	0.00686	0.0150	0.00100	mg/L		11/29/16 1829	12/01/16 1523

Analytical Testing Parameters

Client Sample ID: 232 Left Sink HS-2
Lab Sample ID: J6J0914-02
Sample Type: Grab

Collected By: RBN-Client
Collection Date: 10/13/16
Collection Time: 05:01

Analyses Subcontracted to: Microbac Laboratories, Inc. - Chicagoland

Metals	Result	Limit	PQL	Units	Note	Prepared	Analyzed
Method: EPA 200.8 Rev 5.4							
Lead	0.0161	0.0150	0.00100	mg/L	G	11/29/16 1829	12/01/16 1524

Analytical Testing Parameters

Client Sample ID: 230 Right Sink Boys Room
Lab Sample ID: J6J0914-03
Sample Type: Grab

Collected By: RBN-Client
Collection Date: 10/13/16
Collection Time: 05:03

Analyses Subcontracted to: Microbac Laboratories, Inc. - Chicagoland

Metals	Result	Limit	PQL	Units	Note	Prepared	Analyzed
Method: EPA 200.8 Rev 5.4							
Lead	0.00468	0.0150	0.00100	mg/L		11/29/16 1829	12/01/16 1524

Microbac Laboratories, Inc.

3821 Buck Dr. | Cortland, NY 13045 | 607-753-3403 p | www.microbac.com



Microbac Laboratories, Inc., New York Division

CERTIFICATE OF ANALYSIS

J6J0914

Analytical Testing Parameters

Client Sample ID: 230 Left Sink HS-4
Lab Sample ID: J6J0914-04
Sample Type: Grab

Collected By: RBN-Client
Collection Date: 10/13/16
Collection Time: 05:04

Analyses Subcontracted to: Microbac Laboratories, Inc. - Chicagoland

Metals	Result	Limit	PQL	Units	Note	Prepared	Analyzed
Method: EPA 200.8 Rev 5.4							
Lead	0.0222	0.0150	0.00100	mg/L	G	11/29/16 1829	12/01/16 1525

Analytical Testing Parameters

Client Sample ID: Water Fountain Between 230-232 HS-5
Lab Sample ID: J6J0914-05
Sample Type: Grab

Collected By: RBN-Client
Collection Date: 10/13/16
Collection Time: 05:06

Analyses Subcontracted to: Microbac Laboratories, Inc. - Chicagoland

Metals	Result	Limit	PQL	Units	Note	Prepared	Analyzed
Method: EPA 200.8 Rev 5.4							
Lead	0.00740	0.0150	0.00100	mg/L		11/29/16 1829	12/01/16 1526

Analytical Testing Parameters

Client Sample ID: Bathroom 257 A HS-6
Lab Sample ID: J6J0914-06
Sample Type: Grab

Collected By: RBN-Client
Collection Date: 10/13/16
Collection Time: 05:09

Analyses Subcontracted to: Microbac Laboratories, Inc. - Chicagoland

Metals	Result	Limit	PQL	Units	Note	Prepared	Analyzed
Method: EPA 200.8 Rev 5.4							
Lead	0.00758	0.0150	0.00100	mg/L		11/29/16 1829	12/01/16 1529

Microbac Laboratories, Inc.

3821 Buck Dr. | Cortland, NY 13045 | 607-753-3403 p | www.microbac.com

Page 2 of 15



Microbac Laboratories, Inc., New York Division

CERTIFICATE OF ANALYSIS

J6J0914

Analytical Testing Parameters

Client Sample ID: Bathroom 257 B HS-7
Lab Sample ID: J6J0914-07
Sample Type: Grab

Collected By: RBN-Client
Collection Date: 10/13/16
Collection Time: 05:11

Analyses Subcontracted to: Microbac Laboratories, Inc. - Chicagoland

Metals	Result	Limit	PQL	Units	Note	Prepared	Analyzed
Method: EPA 200.8 Rev 5.4							
Lead	0.00394	0.0150	0.00100	mg/L		11/29/16 1829	12/01/16 1530

Analytical Testing Parameters

Client Sample ID: Water Fountain Between 257 A and D HS-8
Lab Sample ID: J6J0914-08
Sample Type: Grab

Collected By: RBN-Client
Collection Date: 10/13/16
Collection Time: 05:13

Analyses Subcontracted to: Microbac Laboratories, Inc. - Chicagoland

Metals	Result	Limit	PQL	Units	Note	Prepared	Analyzed
Method: EPA 200.8 Rev 5.4							
Lead	<0.00100	0.0150	0.00100	mg/L		11/29/16 1829	12/01/16 1530

Analytical Testing Parameters

Client Sample ID: Teacher Room 220 HS-9
Lab Sample ID: J6J0914-09
Sample Type: Grab

Collected By: RBN-Client
Collection Date: 10/13/16
Collection Time: 05:16

Analyses Subcontracted to: Microbac Laboratories, Inc. - Chicagoland

Metals	Result	Limit	PQL	Units	Note	Prepared	Analyzed
Method: EPA 200.8 Rev 5.4							
Lead	0.00441	0.0150	0.00100	mg/L		11/29/16 1829	12/01/16 1531

Microbac Laboratories, Inc.

3821 Buck Dr. | Cortland, NY 13045 | 607-753-3403 p | www.microbac.com

Page 3 of 15



Microbac Laboratories, Inc., New York Division

CERTIFICATE OF ANALYSIS

J6J0914

Analytical Testing Parameters

Client Sample ID: B212 Bathroom Right Sink HS-10
Lab Sample ID: J6J0914-10
Sample Type: Grab

Collected By: RBN-Client
Collection Date: 10/13/16
Collection Time: 05:19

Analyses Subcontracted to: Microbac Laboratories, Inc. - Chicagoland

Metals	Result	Limit	PQL	Units	Note	Prepared	Analyzed
Method: EPA 200.8 Rev 5.4							
Lead	0.00345	0.0150	0.00100	mg/L		11/29/16 1829	12/01/16 1532

Analytical Testing Parameters

Client Sample ID: B212 Bathroom Left Sink HS-11
Lab Sample ID: J6J0914-11
Sample Type: Grab

Collected By: RBN-Client
Collection Date: 10/13/16
Collection Time: 05:20

Analyses Subcontracted to: Microbac Laboratories, Inc. - Chicagoland

Metals	Result	Limit	PQL	Units	Note	Prepared	Analyzed
Method: EPA 200.8 Rev 5.4							
Lead	0.00543	0.0150	0.00100	mg/L		11/29/16 1829	12/01/16 1532

Analytical Testing Parameters

Client Sample ID: 210 Bathroom Left Sink HS-12
Lab Sample ID: J6J0914-12
Sample Type: Grab

Collected By: RBN-Client
Collection Date: 10/13/16
Collection Time: 05:23

Analyses Subcontracted to: Microbac Laboratories, Inc. - Chicagoland

Metals	Result	Limit	PQL	Units	Note	Prepared	Analyzed
Method: EPA 200.8 Rev 5.4							
Lead	0.0212	0.0150	0.00100	mg/L	G	11/29/16 1829	12/01/16 1533



Microbac Laboratories, Inc., New York Division

CERTIFICATE OF ANALYSIS

J6J0914

Analytical Testing Parameters

Client Sample ID: 210 Bathroom Right Sink HS-13
Lab Sample ID: J6J0914-13
Sample Type: Grab

Collected By: RBN-Client
Collection Date: 10/13/16
Collection Time: 05:24

Analyses Subcontracted to: Microbac Laboratories, Inc. - Chicagoland

Metals	Result	Limit	PQL	Units	Note	Prepared	Analyzed
Method: EPA 200.8 Rev 5.4							
Lead	0.00550	0.0150	0.00100	mg/L		11/29/16 1829	12/01/16 1534

Analytical Testing Parameters

Client Sample ID: Room 207 HS-14
Lab Sample ID: J6J0914-14
Sample Type: Grab

Collected By: RBN-Client
Collection Date: 10/13/16
Collection Time: 05:26

Analyses Subcontracted to: Microbac Laboratories, Inc. - Chicagoland

Metals	Result	Limit	PQL	Units	Note	Prepared	Analyzed
Method: EPA 200.8 Rev 5.4							
Lead	0.0209	0.0150	0.00100	mg/L	G	11/29/16 1829	12/01/16 1536

Analytical Testing Parameters

Client Sample ID: Tech Room 241 HS-15
Lab Sample ID: J6J0914-15
Sample Type: Grab

Collected By: RBN-Client
Collection Date: 10/13/16
Collection Time: 05:28

Analyses Subcontracted to: Microbac Laboratories, Inc. - Chicagoland

Metals	Result	Limit	PQL	Units	Note	Prepared	Analyzed
Method: EPA 200.8 Rev 5.4							
Lead	0.00278	0.0150	0.00100	mg/L		11/29/16 1829	12/01/16 1536

Microbac Laboratories, Inc.

3821 Buck Dr. | Cortland, NY 13045 | 607-753-3403 p | www.microbac.com

Page 5 of 15



Microbac Laboratories, Inc., New York Division

CERTIFICATE OF ANALYSIS

J6J0914

Analytical Testing Parameters

Client Sample ID: Room 243 Faculty Lounge HS-16
Lab Sample ID: J6J0914-16
Sample Type: Grab

Collected By: RBN-Client
Collection Date: 10/13/16
Collection Time: 05:34

Analyses Subcontracted to: Microbac Laboratories, Inc. - Chicagoland

Metals	Result	Limit	PQL	Units	Note	Prepared	Analyzed
Method: EPA 200.8 Rev 5.4							
Lead	0.00278	0.0150	0.00100	mg/L		11/29/16 1829	12/01/16 1537

Analytical Testing Parameters

Client Sample ID: 245 Faculty Bathroom HS-17
Lab Sample ID: J6J0914-17
Sample Type: Grab

Collected By: RBN-Client
Collection Date: 10/13/16
Collection Time: 05:36

Analyses Subcontracted to: Microbac Laboratories, Inc. - Chicagoland

Metals	Result	Limit	PQL	Units	Note	Prepared	Analyzed
Method: EPA 200.8 Rev 5.4							
Lead	0.00344	0.0150	0.00100	mg/L		11/29/16 1829	12/01/16 1538

Analytical Testing Parameters

Client Sample ID: Room 247 Sink HS-18
Lab Sample ID: J6J0914-18
Sample Type: Grab

Collected By: RBN-Client
Collection Date: 10/13/16
Collection Time: 05:38

Analyses Subcontracted to: Microbac Laboratories, Inc. - Chicagoland

Metals	Result	Limit	PQL	Units	Note	Prepared	Analyzed
Method: EPA 200.8 Rev 5.4							
Lead	0.00267	0.0150	0.00100	mg/L		11/29/16 1829	12/01/16 1538

Microbac Laboratories, Inc.

3821 Buck Dr. | Cortland, NY 13045 | 607-753-3403 p | www.microbac.com



Microbac Laboratories, Inc., New York Division

CERTIFICATE OF ANALYSIS

J6J0914

Analytical Testing Parameters

Client Sample ID: Room 247 Water Fountain HS-19
Lab Sample ID: J6J0914-19
Sample Type: Grab

Collected By: RBN-Client
Collection Date: 10/13/16
Collection Time: 05:40

Analyses Subcontracted to: Microbac Laboratories, Inc. - Chicagoland

Metals	Result	Limit	PQL	Units	Note	Prepared	Analyzed
Method: EPA 200.8 Rev 5.4							
Lead	<0.00100	0.0150	0.00100	mg/L		11/29/16 1829	12/01/16 1539

Analytical Testing Parameters

Client Sample ID: B Bathroom Right 252 HS-20
Lab Sample ID: J6J0914-20
Sample Type: Grab

Collected By: RBN-Client
Collection Date: 10/13/16
Collection Time: 05:41

Analyses Subcontracted to: Microbac Laboratories, Inc. - Chicagoland

Metals	Result	Limit	PQL	Units	Note	Prepared	Analyzed
Method: EPA 200.8 Rev 5.4							
Lead	0.0135	0.0150	0.00100	mg/L		11/29/16 1829	12/01/16 1540

Analytical Testing Parameters

Client Sample ID: B Bathroom Left HS-21
Lab Sample ID: J6J0914-21
Sample Type: Grab

Collected By: RBN-Client
Collection Date: 10/13/16
Collection Time: 05:43

Analyses Subcontracted to: Microbac Laboratories, Inc. - Chicagoland

Metals	Result	Limit	PQL	Units	Note	Prepared	Analyzed
Method: EPA 200.8 Rev 5.4							
Lead	0.0231	0.0150	0.00100	mg/L	G	11/29/16 1829	12/01/16 1542



Microbac Laboratories, Inc., New York Division

CERTIFICATE OF ANALYSIS

J6J0914

Analytical Testing Parameters

Client Sample ID: B Bathroom 252 Middle HS-22
Lab Sample ID: J6J0914-22
Sample Type: Grab

Collected By: RBN-Client
Collection Date: 10/13/16
Collection Time: 05:45

Analyses Subcontracted to: Microbac Laboratories, Inc. - Chicagoland

Metals	Result	Limit	PQL	Units	Note	Prepared	Analyzed
Method: EPA 200.8 Rev 5.4							
Lead	0.0102	0.0150	0.00100	mg/L		11/29/16 1829	12/01/16 1544

Analytical Testing Parameters

Client Sample ID: Water Fountain Outside 252 HS-23
Lab Sample ID: J6J0914-23
Sample Type: Grab

Collected By: RBN-Client
Collection Date: 10/13/16
Collection Time: 05:48

Analyses Subcontracted to: Microbac Laboratories, Inc. - Chicagoland

Metals	Result	Limit	PQL	Units	Note	Prepared	Analyzed
Method: EPA 200.8 Rev 5.4							
Lead	0.00498	0.0150	0.00100	mg/L		11/29/16 1829	12/01/16 1544

Analytical Testing Parameters

Client Sample ID: Room 261 Sink HS-24
Lab Sample ID: J6J0914-24
Sample Type: Grab

Collected By: RBN-Client
Collection Date: 10/13/16
Collection Time: 05:50

Analyses Subcontracted to: Microbac Laboratories, Inc. - Chicagoland

Metals	Result	Limit	PQL	Units	Note	Prepared	Analyzed
Method: EPA 200.8 Rev 5.4							
Lead	0.0361	0.0150	0.00100	mg/L	G	11/29/16 1829	12/01/16 1545



Microbac Laboratories, Inc., New York Division

CERTIFICATE OF ANALYSIS

J6J0914

Analytical Testing Parameters

Client Sample ID: Room 265 Sini HS-23
Lab Sample ID: J6J0914-25
Sample Type: Grab

Collected By: RBN-Client
Collection Date: 10/13/16
Collection Time: 05:53

Analyses Subcontracted to: Microbac Laboratories, Inc. - Chicagoland

Metals	Result	Limit	PQL	Units	Note	Prepared	Analyzed
Method: EPA 200.8 Rev 5.4							
Lead	0.0155	0.0150	0.00100	mg/L	G	11/29/16 1829	12/01/16 1546

Analytical Testing Parameters

Client Sample ID: Room 267 Sink HS-26
Lab Sample ID: J6J0914-26
Sample Type: Grab

Collected By: RBN-Client
Collection Date: 10/13/16
Collection Time: 05:58

Analyses Subcontracted to: Microbac Laboratories, Inc. - Chicagoland

Metals	Result	Limit	PQL	Units	Note	Prepared	Analyzed
Method: EPA 200.8 Rev 5.4							
Lead	0.0230	0.0150	0.00100	mg/L	G	11/29/16 1829	12/01/16 1546

Analytical Testing Parameters

Client Sample ID: Girls Bathroom Right 253 HS-27
Lab Sample ID: J6J0914-27
Sample Type: Grab

Collected By: RBN-Client
Collection Date: 10/13/16
Collection Time: 06:00

Analyses Subcontracted to: Microbac Laboratories, Inc. - Chicagoland

Metals	Result	Limit	PQL	Units	Note	Prepared	Analyzed
Method: EPA 200.8 Rev 5.4							
Lead	0.0177	0.0150	0.00100	mg/L	G	11/29/16 1829	12/01/16 1547

Microbac Laboratories, Inc.

3821 Buck Dr. | Cortland, NY 13045 | 607-753-3403 p | www.microbac.com



Microbac Laboratories, Inc., New York Division

CERTIFICATE OF ANALYSIS

J6J0914

Analytical Testing Parameters

Client Sample ID: Bathroom Middle 253 HS-28
Lab Sample ID: J6J0914-28
Sample Type: Grab

Collected By: RBN-Client
Collection Date: 10/13/16
Collection Time: 06:01

Analyses Subcontracted to: Microbac Laboratories, Inc. - Chicagoland

Metals	Result	Limit	PQL	Units	Note	Prepared	Analyzed
Method: EPA 200.8 Rev 5.4							
Lead	0.0180	0.0150	0.00100	mg/L	G	11/29/16 1829	12/01/16 1548

Analytical Testing Parameters

Client Sample ID: Bathroom 253 Left HS-29
Lab Sample ID: J6J0914-29
Sample Type: Grab

Collected By: RBN-Client
Collection Date: 10/13/16
Collection Time: 06:03

Analyses Subcontracted to: Microbac Laboratories, Inc. - Chicagoland

Metals	Result	Limit	PQL	Units	Note	Prepared	Analyzed
Method: EPA 200.8 Rev 5.4							
Lead	0.0271	0.0150	0.00100	mg/L	G	11/29/16 1829	12/01/16 1548

Laboratory

NY: Microbac Laboratories, Inc., New York Division

Definitions

AL: Action Level
RL: Reporting Limit
G: Result fails applicable NYS drinking water standards

Cooler Receipt Log

Cooler ID: Default Cooler Temp: °C

Cooler Inspection Checklist

Custody Seals Intact and/or No Evidence of Tampering	Yes	Containers Intact	Yes
COC/Labels Agree	Yes	Preservation Correct (or not required)	Yes
Received on Ice (or not required)	Yes		

Project Requested Certification(s)

Microbac Laboratories, Inc., New York Division
NY Lab ID No.: 10795
Microbac Laboratories, Inc. - Chicagoland
NY Lab ID No: 12006
PA DEP ID: 68-04863

New York State Department of Health
New York State Department of Health
Pennsylvania Department of Environmental Protection

Microbac Laboratories, Inc.

3821 Buck Dr. | Cortland, NY 13045 | 607-753-3403 p | www.microbac.com



Microbac Laboratories, Inc., New York Division

CERTIFICATE OF ANALYSIS

J6J0914

Report Comments

Samples were received in proper condition and the reported results conform to applicable accreditation standard unless otherwise noted.

Reviewed and Approved By:

A handwritten signature in blue ink, appearing to read "Michael Fifield", is written over a horizontal line.

Michael Fifield
Division Manager
12/06/2016 15:58

Go Green: Contact Michael Fifield to set up email reporting and invoicing options.

The data and information on this, and other accompanying documents, represents only the sample(s) analyzed. This report is incomplete unless all pages indicated in the footnote are present and an authorized signature is included. For any feedback concerning our services, please contact Michael Fifield, Project Manager at michael.fifield@microbac.com. You may also contact Michael Fifield, Managing Director at michael.fifield@microbac.com or Robert Crookston, President at robert.crookston@microbac.com.

3021 Buck Drive
Cortland NY 13046
Phone: (607) 765-3408 Fax: (607) 765-3416
NY #10706, EPA #NY000936

Microbac Laboratories, Inc. CHAIN OF CUSTODY

Samples must be returned on ice

Client Information				Billing/Invoice:		Analysis Requested		Receiving Info (Lab Use Only)	
Name:	Cortland CSD			Cortland CSD				Lot:	YES NO
Address:	55 HS							Cooler:	YES NO
Contact:								Sample Temp:	YES NO
Phone:								Cooler Seal:	YES NO
Project:								Pickup:	YES NO
Quote ID:	PO#:							Dropoff:	G W
Rush TAT Bus. Days: <2 2-5 5-7 7-10				Date Req.:				Accepted?	YES NO
Release to DOH: Yes								Container Material	
Email Results: Yes				R.MARTIN@CORTLANDSCHOOLS.ORG				Container Size (in ml)	
Fax Results: Yes				K.WALDBY@CORTLANDSCHOOLS.ORG				Preservative	
								Comments/Field Data	
Sample Information				Matrix		Number of Containers for Analysis Requested			
Description/Location	Date	Time	Initial	Type					
1 HS-1 ^{Stork} 232 - GIRLS Room	OCT, 13	5:00 AM	RBN	BW					
2 HS-2 232 ^{Stork} LEFT	10/13/16	5:01 PM	RBN	GBW					
3 ^{Stork} 230 RIGHT	10/13/16	5:03	RBN						
4 HS-4 230 LEFT	10/13/16	5:04	RBN						
5 WATER FOUNTAIN HS-5	10/13/16	5:06	RBN						
BETWEEN 230-232									
6 BATHROOM	10/13/16	5:09	RBN						
257 A									
7 BATHROOM	10/13/16	5:11	RBN						
257 B									
8 WATER FOUNTAIN HS-8	10/13/16	5:13	RBN						
BETWEEN 257 A + B									
Print Name and Company				Signature		Date/Time		Comments	
Sampled: Rick B Niederhoffer				Rick B Niederhoffer		10/13/16 7:05 AM			
Received: BOB MARTIN CSDSD				Bob Martin		10/14/16 7:03			
Received: Hayma Dawson				Hayma Dawson		10/14/16 9:55			
Received:									
Received:									
Received:									

3021 Buck Drive
Corland NY 13046
Phone: (607) 763-3403 Fax: (607) 763-3416
NY #10708, EPA #NY700896

Microbac Laboratories, Inc. CHAIN OF CUSTODY

Samples must be returned on ice

MNY Workorder #

Client Information				Billing/Invoice:		Analysis Requested		Receiving Info (Lab Use Only)	
Name: CFCSD								Ica: YES NO	
Address: 3545								Cooler: YES NO	
Contact:								Sample Temp:	
Phone:								Cooler Seal: YES NO	
Project:								Pickup: YES NO	
Quote ID:								Dropoff: C W	
Rush TAT Bus. Days: <2 2-5 6-7 7-10								Accepted? YES NO	
Released to DOH: Yes								Container Material	
Email Results: Yes								Container Size (in Mi)	
Fax Results: Yes								Preservative	
Sample Information				Number of Containers for Analysis Requested		Comments/Field Data			
Description/Location	Date	Time	Initial	Matrix	Type				
1 TEACHER HS-9 ROOM 220	OCT 13TH	5:16	RBN	SW	Cond				
2 B212 BATHROOM RIGHT HS-10	10/13/16	5:19	RBN						
3 B212 BATHROOM HS-11 LEFT	10/13/16	5:20	RBN						
4 210 BATHROOM LEFT HS-12	10/13/16	5:23	RBN						
5 210 BATHROOM RIGHT HS-13	10/13/16	5:24	RBN						
6 Room 207 HS-14	10/13/16	5:26	RBN						
7 TEACHER Room 241 HS-15 RM 243	10/13/16	5:28	RBN						
8 FACULTY LOUNGE HS-16	10/13/16	5:34	RBN						
Print Name and Company				Signature		Date/Time			
Sampled: Rick Niederhofer				Rick Niederhofer		10/13/16 7:03			
Received: BOB MARTIN SBCSD				B Martin		10/14/16 7:15			
Received: Hayman Dawson				Hayman Dawson		10/14/16 9:55			
Received:									
Received:									
Received:									

3021 Buck Drive
Corland NY 13045
Phone: (807) 763-3408 Fax: (807) 763-3416
NY #10705, EPA #NY000636

Microbac Laboratories, Inc. CHAIN OF CUSTODY

Samples must be returned on ice

MNY Workorder #

Client Information				Billing/Invoice:		Analyte Requested		Receiving Info (Lab Use Only)	
Name:	C B S S D							Ice:	YES NO
Address:	35145							Cooler:	YES NO
Contact:								Sample Temp:	
Phone:								Cooler Seal:	YES NO
Project:								Pickup:	YES NO
Quote ID:								Dropoff:	C W
Rush TAT Bus. Days: <2 2-5 6-7 7-10								Accepted?	YES NO
Release to DOH: ☒								Container Material:	
Email Results: Yes	RMS-11 @ CORLAND 3040001, 000							Container Size (in ml)	
Fax Results: Yes	KWAJ-13 @ CORLAND 3040001, 000							Preservative	
Sample Information				Matrix		Number of Containers for Analyte Requested			
Description/Location	Date	Time	Initial	Type					
1 245 FACULTY ^{HS-11} BATHROOM	10/13/16	5:36	RBN	DW					
2 RM 247 SINK ^{HS-13}	10/13/16	5:38	RBN	SW					
3 HS-19 WATER	10/13/16	5:40	RBN						
4 B-BATHROOM 252	10/13/16	5:41	RBN						
5 B-BATHROOM 252	10/13/16	5:43	RBN						
6 B-BATHROOM 252	10/13/16	5:45	RBN						
7 WATER FOUNTAIN ^{HS-23} OUTSIDE 252	10/13/16	5:48	RBN						
8 RM 261 SINK ^{HS-24}	10/13/16	5:50	RBN						
Print Name and Company					Signature	Date/Time		Comments	
Sample: Rick Niederhoffer					Rick Niederhoffer	10/13 7:05			
Received: BOB MARTIN C B S S D					BOB MARTIN	10/13 7:07			
Received: Hayma Damm					Hayma Damm	10/14/16 9:55			
Received:									
Received:									
Received:									

3821 Buck Drive
Coneland NY 13046
Phone: (607) 769-3403 Fax: (607) 769-3410
NY #10786, EPA #NY000936

Microbac Laboratories, Inc. CHAIN OF CUSTODY

Samples must be returned on ice

MNY Workorder #

Client Information			Billing/Invoice:		Analysis Requested		Receiving Info (Lab Use Only)	
Name:	CACS						Ice:	YES NO
Address:	5515						Cooler:	YES NO
Contact:							Sample Temp:	
Phone:							Cooler Seal:	YES NO
Project:							Pickup:	YES NO
Quote ID:							Dropoff:	C W
Rush TAT Bus. Days: <2 2-5 6-7 7-10							Accepted?	YES NO
Release to DOH: Yes							Container Material	
Email Results: Yes							Container Size (in Mi)	
Fax Results: Yes							Preservative	
Sample Information			Number of Containers for Analysis Requested		Commercial/Field Data			
Description/Location	Date	Time	Initial	Matrix Type				
1 Hs-25 Rm 26.5 Sink	10/13/16	5:53	RBN	DUN GAS				
2 Hs-26 Rm 26.7 Sink	10/13/16	5:58	RBN					
3 GIRLS BATHROOM HS-27 253 Right	10/13/16	6:01	RBN					
4 BATHROOM HS-28 253 Middle	10/13/16	6:01	RBN					
5 BATHROOM HS-29 253 Left	10/13/16	6:03	RBN					
6								
7								
8								
Print Name and Company					Signature	Date/Time		
Rick Niederlofer					Rick Niederlofer	10/13 7:06 PM		
Bob Martin CACS					Bob Martin	10/13 7:06 PM		
Hayma Dawson					Hayma Dawson	10/14/16 9:55		
Received:								
Received:								
Received:								
Received:								
Received:								